

# March 2008 Maintenance Report

	big trash	Broken Glass	graffiti removal	Landscape services	litter	other request	Sweeping	Total
2700 E	2			1	24		6	33
2800 E	1				11		7	19
2800 W				3	10		1	14
2900 E	2				15		6	23
2900 W				10	4			14
3000 E	4				15		5	24
3000 W				9	5			14
3100 E	3		1		7		10	21
3100 W				8	6	1		15
3200 E	5	2			13		8	28
3200 W				8	7			15
3300 E	2	1			11		7	21
3300 W				10	5			15
3400 E	4				14		7	25
3400 W				13	6		1	20
3500 E	5				15		8	28
3500 W				9	10		1	20
3600 E	4			1	17		5	27
3600 W	2			13	10		1	26
3700 E	6			3	14		6	29
3700 W				12	8			20
3800 E	12	1	1	3	28		1	46
3800 W	5			3	13			21
3900 E	20	1		3	20		2	46
3900 W	20			2	15		1	38
4000 E	8	1		3	12		1	25
4000 W	15	1	1	2	10			29
4100 E	11				12			23
4100 W	19		1		5			25
4200 E	13				10			23
4200 W	16				5			21
4300 E	10	1	1		10			22
4300 W	18				7			25
4400 E	11				8		1	20
4400 W	14				7		1	22
4500 E	9				6			15
4500 W	15				8			23
4600 E	13				4			17
Total	269	8	5	116	407	1	86	892