

September 08 AMA Service Report

	big trash	Broken Glass	Bus Shelter	graffiti removal	Landscape services	litter	maintenance bus shelter	other request	Sweeping	Total
2700 E					13	10				23
2800 E					7	5	1			13
2800 W					7	5				12
2900 E					3	8	1			12
2900 W			1		9	5				15
3000 E	1				3	14				18
3000 W					7	7				14
3100 E			1		2	9	4			16
3100 W			1		5	7	2			15
3200 E					5	7	4			16
3200 W			1		1	7	7			16
3300 E					6	10				16
3300 W					9	6				15
3400 E					3	8	5			16
3400 W					7	7	1	1		16
3500 E					5	13	1			19
3500 W					11	12	1			24
3600 E					5	13				18
3600 W	1	1			11	10				23
3700 E	4				5	14				23
3700 W		1			6	9		2	1	19
3800 E	10			1	2	10	1	1		25
3800 W	7				1	7			1	16
3900 E	31	1		1	1	19				53
3900 W	32	1			1	6				40
4000 E	36				1	11				48
4000 W	54					6				60
4100 E	24					6			3	33
4100 W	18					3				21
4200 E	46					7			2	55
4200 W	23					3				26
4300 E	31	1			1	6		1		40
4300 W	41	1	1			5				48
4400 E	18	1				6			1	26
4400 W	20					3			1	24
4500 E	17	1			1	5				24
4500 W	22				1	1			1	25
4600 E	13				2	7			1	23
Total	449	8	5	2	141	297	28	5	11	946